



SERVICE PART LIST FOR STYLE #922MONITOR

ITEM NO.	PARTS DESCRIPTION	PARTS NO.	QUANTITY
1	SCREW	S0353	8
2	MOTOR HOUSNG	A7919	1
3	PLATE	A7948	2
4	WORM SHAFT	F1108	2
5	PIN	F0278	2
6	MONITOR INLET BODY	A7921	1
7	SCREW	S0112	4
8	MONITOR OUTLET BODY	A7920	1
9	PIN	F0163	2
10	HEXAGON NUT	F1107	2
11	O-RING	O0248	4
12	BALL BEARING	F0076	74
13	O-RING	O0360	2
14	MOTOR HOUSING	A7922	1
15	MONITOR BASE	A7934	1
16	ELECTRIC NOZZLE	A7949	1